


In instruments with serial no. below 1204806 the following fault may occur:



The wires through the P.C. Board (refer to the picture above) may be too long. This cause in some cases shortcircuit to chassis which again disturb the control between The Type 2306 and 1625.

Please check the instruments you may have at your stock.